



2017 Winter Storage - \$30.00 per month

Winterization Rates for Stern Drives, Inboards, V-drives, and PWCs may increase approx. \$52.00 after November 15 due to Colder Weather

Stern Drives / Inboards / V-Drives / PWC

Engine (Cylinders)	Service Cost	Lower Unit Gear Lube (Includes new drain screw seals)	Fogging Oil	Anti-Freeze	Fuel Stabilizer	Basic Winterize	Oil Change & Filter	Winterize w/ Oil Change	U-joint & Alignment	Complete Winterize
4	150.00	Alpha I - 46.00	9.99	24.00		254 - 268	110.00	364 - 378	Alpha - 110 Bravo, OMC, Volvo - 145	474 - 488
6	175.00	Bravo I & III - 56.00	9.99	24.00	16 oz.	278 - 292	120.00	398 - 412		508 - 522
8	200.00	Bravo II - 63.00	9.99	24.00	15.99	304 - 326	120.00	424 - 446		534 - 556
* OBWP	225.00	OMC +Volvo - 52.00	9.99	24.00		317 - 339	120.00	437 - 459		582 - 598
Inboard	225.00	Cobra & Volvo SX - 60.00	9.99	24.00	32 oz.	284 - 298	120.00	404 - 418		N/A
V-Drive	250.00	N/A	9.99	24.00	25.99	309 - 323	120.00	429 - 445		N/A
Twin Jet	250.00	N/A	19.98	48.00		362 - 378	240.00	584 - 598		N/A
PWC	125.00	N/A	9.99	24.00	8.99	174 - 184		N/A		N/A

* Note: OBWP = On-Board Water Pump: Any boats with an on-board water pumps will fall under this category regardless of engine size (cylinders). Mercruisers w/ Bravo Outdrives, Yamaha, Volvo, and Volvo SX will fall in this category

Basic Winterization Includes

- Adding Stabilizer to Fuel Tank
- Draining Engine Block, Manifolds and Coolers of Water
- Running Engine in Propylene Glycol Tank (Antifreeze)
- Fogging Carburetor and Cylinders
- Changing Lower Unit Gear Lube
- Checking & Filling Closed Cooling Systems
- Greasing External Fittings
- Disconnecting Battery (or Turning Battery Switch Off)
- Pulling Prop, Checking for Obstructions, Greasing
- Filling Fuel Tank to Prevent Condensation (if requested)

With Oil Change

- Engine Oil and Filter Replacement

U- Joint & Alignment Service

- Removing Outdrive
- Checking Engine Alignment
- Inspecting and Greasing Gimbal Bearing
- Inspecting and Greasing Universal Joints
- Inspecting Bellows

All 3 Services make up a Complete Winterize

Outboards

Engine (Cylinders)	Service Cost	Lower Unit Gear Lube	Fogging Oil	Fuel Stabilizer	Basic Winterize	4-Stroke Only	Full 4-Stroke Winterize
1	75.00	14.00	9.99	8 oz.	109 - 119	N/A	N/A
2 & 3	90.00	21.00	9.99	8.99	138 - 148	115.00	253 - 263
4	95.00	23.00	9.99	16 oz.	148 - 158	125.00	273 - 283
6	100.00	25.00	9.99	15.99	158 - 168	125.00	283 - 293
8	100.00	27.00	9.99	32 oz.	161 - 171	125.00	286 - 296
				25.99			

Interior Cleaning

\$45.00 per hour + Cleaners

Bottom Cleaning

Boat Type	Service Cost
Pontoons	130.00
Tritoons	160.00
V-hull	8 Per Foot

A fee of \$30.00 is to be added for pulling the boat from water and replacing if this Service is required

Road Trips

Location	Cost
Lake Anna	85.00
Lake Caroline	85.00
Lake of the Woods	85.00
Fawn Lake	85.00
Blue Ridge Shores	85.00
Lake Monticello	95.00

Trip fees cover travel to and from site. Time spent at the site will be billed

Shrink Wrapping

Boat Type	Cost Per Foot	Minimum Cost
Bow Riders	10.00	200
Deck	11.00	210
Cuddy Cabins	11.00	210
Pontoons	11.00	220
Over 26'	Shop Quote	

Some boats, due to design, require extensive support systems that will be billed in addition to Shrink Wrap Rates

All Shrink Wraps Include 2 Mildew Control Bags

Pontoon, Tritoon Blocking

Boat Type	Pull From Water & Set on Blocks In Fall	Remove From Blocks & DeWinterize In Spring
Pontoons	75.00	105.00
Tritoons	95.00	125.00

While on Blocks, Customer will be billed @ Winter Storage Rate
Tritoon Blocking cannot be done off-site
Pontoon Blocking off-site will require a Road Trip fee

Note: Additional charges will be added for any delays that prevent the mechanic from starting the boat such as the absence of Keys - Dead or Weak Battery - Flat Tire(s) - Trim Failure - Motor Starting / Running Problems - Excessive Cover-Up of Boat - Removing boat from Water - etc.... If the Outdrive is a problem to remove from the boat due to corrosion, extra time will be added.

Sturgeon Creek Marina

Lake Anna, Va

Winterize Request Form

Customer Information

Name		Date: ___/___/___
Address		
Cell Phone	Home Phone	Additional Phone

Boat Information

Boat Make & Model		Registration Number: ___-___-___
Engine Type <input type="checkbox"/> Outboard (2-Stroke) <input type="checkbox"/> Outboard (4-Stroke) <input type="checkbox"/> Inboard/Outboard <input type="checkbox"/> Inboard <input type="checkbox"/> "V" Drive <input type="checkbox"/> PWC		
Engine Make, Model & HP		Date Engine was Last Ran: ___/___/___
Boat Location	Key Location (In Ignition is Preferred)	Running Condition

Please Check the Services that you would like provided: (See Front for Rates)

Standard Winterize Services			
<input type="checkbox"/> Basic Winterize	<input type="checkbox"/> Winterize w/ Oil Change	<input type="checkbox"/> Complete Winterize	<input type="checkbox"/> Winter Storage
<input type="checkbox"/> Shrink Wrap	<input type="checkbox"/> Bottom Cleaning	<input type="checkbox"/> Anode Replacement	<input type="checkbox"/> Prop Repair
<input type="checkbox"/> Impeller Replacement	<input type="checkbox"/> Grease Wheel Bearing	<input type="checkbox"/> Re-Pack Wheel Bearings <small>Approx \$80 Per Wheel</small>	<input type="checkbox"/> Interior Clean <small>Recommended In Spring</small>

Does Your Boat have an On-board Water System of any type (ex: sink, wash down, etc...) Yes No

Do You Want Sturgeon Creek to Winterize the Water System? Yes No

Please List Any Additional Work Needed or Requests

Customer Signature: _____ Date: ___/___/___